



NEW BUILD

REMODEL

CARPENTRY

FIXTURE
INSTALLATION

SERVICE AND
REPAIRS

CABINETS

Photos of Grocery Store
Emergency Repair



Broken Beam



Open Roof



New Beam

ARE YOU PREPARED FOR AN EMERGENCY? EFA IS YOUR ON-THE-SPOT RESOURCE FOR ANY EMERGENCY TO YOUR BUILDING. *READ ON...*

It was Friday afternoon of the Labor Day holiday weekend. Students at the college town of Chico, California were celebrating the end of classes and were out shopping for party supplies. Without warning, **a beam supporting the roof of the favorite local supermarket collapsed**, prompting evacuation of the store and a lockout by the local fire dept.

Within hours, our crews were on site with an engineer. Working through the night, we surveyed the damage with the engineer. At 7AM the next morning, we began installation of temporary shoring in order to support the roof and ensure the building would be safe for the public. By 6PM, city officials and the fire department deemed the structure safe and doors were reopened to the public. **Thanks to EFA, one of the busiest shopping weekends of the year was salvaged for this business.**

After approval of a budget for repairs, we returned for a permanent repair. The job involved removing a 40' x 80' section of roof, hoisting the damaged beam and trusses through the opening, and lowering and installing a replacement beam and trusses specified by the engineer. **This was all accomplished while the store remained open for business.**

- Emergency repairs
- Major renovations while you remain open for business
- Safety for your employees and your customers
- After-hours work

After doing this over and over for the past 65 years, we've built a reputation of being the folks you can count on.

www.efainc.com

ADDRESS

1066 BEECHER STREET
SAN LEANDRO, CA 94577

OFFICE

510-430-8404
800-454-8404

FAX

510-430-2561

EMAIL

kristin@efainc.com